

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,934,180 B1  
APPLICATION NO. : 10/675042  
DATED : August 23, 2005  
INVENTOR(S) : Darryl G. Walker

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 14, lines 11-12, "second channel control side gate" should be changed to  
--second channel side control gate--

Signed and Sealed this

Thirty-first Day of July, 2007



JON W. DUDAS  
*Director of the United States Patent and Trademark Office*